

B - (5)

Noted and Registered at
Serial No. 6298
Date 23 JUL 2021

A F F I D A V I T



I, **Adv. Ramesh Suresh Rodgi**, Age - 36 Years,
Occupation - Advocate, R/o - 816, North Kasba,
Solapur solemnly affirm and state as under,

That, I have translated Certificate issued by
Executive Engineer, Public Works Division, Panvel to
the Indian Model School and Junior College, Ulwe,
Navi Mumbai, Outward No. P.W.D./ Panvel/ Resha
1282 dt. 09/04/2021 which is in Marathi Language
into English.

This is verbatim from Marathi to English and it is
true and correct to the best my knowledge, belief and
information and the testimony thereof. I have affixed
my signature and seal there under at Solapur.

This affidavit Dt. 23/07/2021


23 JUL 2021

Affiant

(Adv. Ramesh Suresh Rodgi)

Advocate

Ramesh S. Rodgi
Advocate
816, North Kasba, Solapur
Dist. No. 9225331016





BEFORE ME

M 23/7/21
Basavaraj L. Savalg
NOTARY GOVT OF INDIA
SOLAPUR

Shri. *M. Ramesh S*
Resha M. Jadhav
Signed before me who identified by
shri. *B. L. Savalg*

Noted and Registered


Serial No. _____ Date _____



NOTARIAL NOTARIAL NOTARIAL NOTARIAL NOTARIAL

प्रमाणपत्र


प्रमाणित करण्यांत येते की इंडीयन मॉडेल स्कुल अँड ज्युनियर कॉलेज, प्लॉट नं.१७८, सेक्टर -१९, उलवे, नवी मुंबई या शाळेच्या इमारतीची दिनांक ०६/०३/२०२१ रोजी प्रत्यक्ष पहाणी केली असता सदर इमारतीचे बाहेरील गिलावा सर्वसाधारणतः सुस्थितीत आढळला. तसेच इमारतीचे आतील पहाणीत कोणतेही मोठे स्ट्रक्चरल डिस्ट्रेस दिसून आले नाही. इमारतीचे स्तंभ, तुळ्या, लादया इत्यादीमध्ये कोणतेही रस्ट सँग अथवा सटेलमेंट आढळून आले नाहीत. सर्वसाधारणपणे सदर इमारत सुस्थितीत आढळून आली.



सहाय्यक अभियंता श्रेणी-१
सा.बां. उपविभाग क्र.१,
पनवेल.

कार्यकारी अभियंता
सार्वजनिक बांधकाम विभाग
पनवेल.

जा.क्र. सा.बां.वि/पनवेल/रेशा १२८२
कार्यकारी अभियंता यांचे कार्यालय,
सा.बां.विभाग, कार्यालय,
दिनांक. ०८.०४.२०२१



Certificate

This is to certify that the building of Indian Model School & Junior College, Plot No. 178, Sector-19, Ulwe, Navi Mumbai has been inspected on 06/03/2021 and it was found that the outer plaster is in proper condition. The building was inspected from inside also and no major structural distress was found. All the pillars, beams, floors of the building are proper and no rust sags or settlements were found. Overall the building is in proper condition.

Seal

Sd/-

Assistant Engineer Category 1
P.W.D. Subdivision No.1
Panvel

Sd/-

Executive Engineer
Public Works Division
Panvel

Outword No. P.W.D. / Panvel / Resha 1282

Office of the Executive Engineer,

P.W. Division, Office,

Date : 09-04-2021



A. Kulkarni
Principal
Indian Model School & Jr. College
Ulwe, Navi Mumbai

A. Kulkarni
MANAGER
Indian Model School & Junior
College, Ulwe, Navi Mumbai